




1/10



2/10




FIG. 4A




FIG. 4B

3/10





FIG. 5A




FIG. 6A




FIG. 6B




FIG. 6C




FIG. 6D




FIG. 7A




FIG. 7

5/10




FIG. 8

6/10





FIG. 8A

DETAIL OF THREADS



CONSEQUENCE OF THREADS  
 WHICH ARE TOO SOFT  
 (RUBBERY) IN COMPRESSION

FIG. 8B

7/10




FIG. 9

8/10





FIG. 10

10/10





Creation date: 09-22-2003  
Indexing Officer: EHAILU - ELIZABETH HAILU  
Team: OIPEScanning  
Dossier: 10661822

Legal Date: 09-02-2003

No.	Doccode	Number of pages
1	TRNA	2
2	SPEC	18
3	CLM	9
4	ABST	1
5	DRW	9

Total number of pages: 39

Remarks:

Order of re-scan issued on .....